

Technical drawing of a door assembly showing six cross-sections (A-F) with dimensions and material hatching.

Section A: Shows the door frame and hinge area. Dimensions: 57, 40, 10, 37, 20, 14, 42, 40. Hatching: 3, 10, 16, 27, 5, 3, 50.

Section B: Shows the door frame and hinge area. Dimensions: 40, 15, 42, 40. Hatching: 3, 10, 16, 27, 5, 3, 50.

Section C: Shows the door frame and hinge area. Dimensions: 57, 40, 15, 44, 10, 9, 14, 42, 40, 25, 42, 20. Hatching: 3, 10, 16, 27, 5, 3, 50.

Section D: Shows the door frame and hinge area. Dimensions: 40, 15, 42, 40. Hatching: 3, 10, 16, 27, 5, 3, 50.

Section E: Shows the door frame and hinge area. Dimensions: 57, 40, 10, 37, 20, 14, 42, 40. Hatching: 3, 10, 16, 27, 5, 3, 50.

Section F: Shows the door frame and hinge area. Dimensions: 40, 15, 42, 40. Hatching: 3, 10, 16, 27, 5, 3, 50.

REM

SKALA 1:1

REMONT ZESPOŁU SAKRALNEGO W NARUSZEWIE